Dealer Service Information Service Bulletin No. <u>95-003</u>

OPTIONAL

- **A** RECOMMENDED Not for general distribution
- MANDATORY

TIMELINE VISTA, INC. 1755 LA COSTA MEADOWS DRIVE, SUITE B SAN MARCOS, CA 92069 TEL. 760-761-4440 (FAX 760-761-4449) SUPPORT@DIGAUDIO.COM

System Supervisor Main PCB Modification

DATE: 04/05/95

- **MODEL:** System Supervisor Unit (SSU)
- **REVISION:** All
- **SERIAL NO:** All Units prior to Serial Number 243
- SOFTWARE: All

REQUIRED TOOLS:

Static safe workstation Phillips screwdriver Grounding wrist strap

DESCRIPTION:

Recently some SSU's were found to be experiencing problems locking with Lynx-2 modules. This is due to the SSU not sending out the correct 30Hz Bipolar Output.

PROCEDURE:

- 1. Turn off the SSU and disconnect all cables from the rear panel. Place the SSU on a static safe workstation. Ground yourself and the workstation anti-static mat.
- 2. Remove the eight phillips screws securing the top cover of the SSU. Remove the top cover.
- 3. On the Main PCB, locate U26 and U63. If these IC's are SGS Thompson HCF 4520 parts, contact TimeLine for an RMA Number, they must be replaced.
- 4. Replace the top cover on the SSU. Insert and tighten the screws.

Dealer Service Information Service Bulletin No. <u>95-003</u>