

# SSL Interface Card Manual Supplement No. <u>MS 93-008</u>

TIMELINE VISTA, INC. 1755 LA COSTA MEADOWS DRIVE, SUITE B SAN MARCOS, CA 92069 TEL. 760-761-4440 (FAX 760-761-4449) SUPPORT@DIGAUDIO.COM

# SSL Interface Card Software Release Notes

DATE: 09/07/00

- MODEL: System Supervisor Unit with SSL Interface Card
- **REVISION:** All
- SERIAL NO: All
- SOFTWARE:**PROM Name**<br/>SSLVersion<br/>1.42
- MANUAL: 73A006

**DESCRIPTION:** 

## SSL 1.42

The following improvements have been made in the SSL 1.42 software release:

• The SSL computer interface has been made more robust and has improved handling of communications time outs.

### Software History

### SSL 1.42a

This software version includes a change for the Jog Shuttle Wheel. Any existing sites that have jog wheels connected must flip two pins to retain proper functionality. The change can be made on the encoder itself by flipping the yellow and orange wires, or at the 15-pin D connector by flipping pins 1 and 9.

Manual Supplement No. <u>MS 93-008</u>