

Service Bulletin NO. 91-007

TIMELINE VISTA, INC.
1755 LA COSTA MEADOWS DRIVE, SUITE B
SAN MARCOS, CA 92069
Tel. 760-761-4440
(FAX 760-761-4449)
SUPPORT@DIGAUDIO.COM

SSL SYNCHRONIZER DISPLAY


DATE: 8/2/91
MODEL: SSL Synchronizer Display, part number CF82E145
REVISION: All
SERIAL NO: All
SOFTWARE: All

DESCRIPTION:

This modification increases the brightness of the LEDs on the SSL Sync Panel when used with the Lynx System Supervisor. It is performed on the Synchronizer Display board in the SSL console.

PROCEDURE:

1. Remove the Synchronizer Display board from your SSL console.
2. On the solder (back) side of PCB install a wire jumper shorting R1 and R2.



3. Re-install the Synchronizer Display board into your SSL console.